

2014 TOYOTA Ractis

Reg: 19144

This appraisal has been prepared by the New Zealand Automobile Association acting as a technical consultant for the Motor Vehicle Dealer named below and not for any prospective purchaser of the vehicle and as such is performed "In Trade" under the Consumers Guarantees Act. The Appraisal to which this report refers is external and visual only and of necessity does not include defects or conditions of internal mechanisms that may be discovered by subsequent dismantling. The report applies to the condition of the vehicle at the time of appraisal.

Purchasers could obtain greater protection from a full AA Vehicle Inspection

Vehicle Inspection Centre: Hamilton Mobile Inspections

22246811-1

This report has been carried out for:

5, Norris Avenue, Te Rapa

Inspection Date: 27 May 2026

Reg Expiry:

VIN: 7AT0H652X26044615

Expiry Date: 27 Jul 2026

WOF: 20 May 2027

Origin: Import

Odometer: 48134 Kms

RUC Expiry:

Year First Reg:

Items Covered By This Inspection As Applicable

Brake System Visual External Only

- 1 Brakes
- 2 Brakes - Under Body

Cooling System

- 3 Radiator
- 4 Water Pump (Where Visible)

Electric Accessories / Lamps

- 5 Lamps

Electrical

- 6 Battery
- 7 Horn

Engine Ancillaries

- 8 Fuel System
- 9 Lubricants (Eng/Trans)
- 10 Engine
- 11 Air Filter

Engine Audible Noises

- 12 Engine Noise

External Items

- 13 Windsceen Washer
- 14 Windscreen Wiper
- 15 Rear View Mirror
- 16 Ancillary Items

Fuel System

- 17 Fuel Filler

Interior

- 18 Tools and Accessories

Road Test

- 19 Air Conditioning
- 20 Engine Test
- 21 Exhaust Test
- 22 Foot Brake Test
- 23 Transmission Test
- 24 Handbrake Test
- 25 Steering Test

Suspension

- 26 Suspension
- 27 Wheels
- 28 Hubs


Tyres

- 29 Tyres

Underside


- 30 CV Joints
- 31 Engine
- 32 Exhaust
- 33 Axle
- 34 Structure
- 35 Transmission
- 36 Differential
- 37 Driveshaft
- 38 Steering - Under Body

Tyre Condition



Legal Minimum 1.5mm for Standard Tyres, 4mm for Snow Tyres

12v ELECTRICAL SYSTEM TEST



Defects Found During Inspection

General Condition

Sound : Vehicle is in above average condition for age and mileage